

1.指令不支持，删除

GENERAL	Added AT+QOTG to switch USB master and slave mode.	R06A13_02.20.00
<div>AT+QOTG=? ERROR AT+QOTG? ERROR AT+QOTG=1 ERROR AT+QOTG=1 ERROR</div>		

2.内部指令，不对外发布，删除

TCP/UDP	Added AT+QIKALIVE .	R06A0807.01.00
---------	----------------------------	----------------

3.不支持的指令，删除

TCP SSL	Added AT+QISLSEND=0,0 to query the cache status of the AT+QSSSEND.	R06A06_00.01.0006 R06A06_06.01.0006 R06A06_0
<div>AT+QSSLOPEN=1,1,0,"58.40.120.14",6061 OK +QSSLOPEN: 0,0 AT+QSSLSEND=0 > 123 SEND OK +QSSLURC: "recv",0 AT+QISLSEND=0,0 ERROR AT+QSSLRCV=0,1500 +QSSLRCV: 3 123 OK AT+QISLSEND=0,0 ERROR</div>		

4.不支持的指令删除

HTTP	password to log in http server.	ERROR AT+QCFG="w_disable_pin",1 ERROR AT+qcfg="w_disable_pin" ERROR ATI+CSUB;+QGMR Quectel EC25 Revision: EC25EFAR06A17M4G
GENERAL	Added AT+QCFG="w_disable_pin" to configure whether w_disable pin is used to indicate status of RF PA. The function was disabled by default.	
GENERAL	Refreshed NV 947/5895/7145 as DT required automatically.	

5.该指令不对外，删除

NETWORK	Added the AT+QRXPPWR to query the main receiving and diversity reception signal parameters.	R02A05
---------	--	--------

		U5.
NETWORK↵	Added AT+Q_RXPWREX ↵	R0
		05.
	Added ATS12 to configure the interval for +++ to exit pass-through	R0

6.非 AT 指令不加粗

	successfully, which led to the abnormal disconnection of MQTT.↵	U.20.200↵
MQTT↵	Fixed the problem related to URC that multiple +QMTPUBEX: returned.↵	R06A17_20.20 0.20.200↵
TCP SSL↵	Solved the problem that the format of the parameter <op> of dtls and the parameter <version> of dtlsversion were incorrect returned by AT+QSSLCFG=? ↵	R06A09_01.00 1.01.001↵
		1.01.001↵
GENERAL↵	Optimized AT+QCFG="ppp/sleep_ri" to solve the problem of no sleep_ri jitter after receiving PPP data.↵	R06A09_01.00 1.01.001↵
GENERAL↵	Corrected the valid range of parameter <temp_threshold> of AT+QCFG="thermal/txpwrlimt" .↵	R06A08_0 7.01.007↵
		R06A07_0
SMS↵	Support to execute AT+CNMA after receiving +CMT message when <mode> of AT+CNMI is set to 1 or 2 and type of message service is set as 1 by AT+CSMS .↵	R06A02↵
FTP↵	Fixed the bug that executing the AT+QFTPPUT to upload from UFS has opened the file, is not an error and to upload, expected return is ERROR .↵	R02A04↵
FTP↵	Fixed the bug that the AT+QFTPPUT parameter is set to 2, the implementation of successful and be able to upload files, expected return is ERROR .↵	R02A03↵

7.8814codec 不维护了，删除

	server in 005.↵	
GENERAL↵	Support sleep mode for NAU8814 . Fix the power issue when voice call is disconnected.↵	R06A02↵

8.更新驱动版本到最近使用的版本